Work Order ID 114787  Thursday, March 13, 2014 2:31:11 PM				*114		Page 1						
Item ID: Revision ID: Item Name: Start Date: Required Date:	D3636-11  Shoulder Harness  3/12/2014 Start Qty: 3/13/2014 Req'd Qty:		1* 1*	Accept	*N900  Cust Item II Customer:			<b>)</b> * :	Setup	Start Stop	ı V.	S1* S2*
Reference:	RMA RA111689		· · · · · · · · · · · · · · · · · · ·				_	-	<b>.</b>	Storet		_
Approvals:	Process Plan:QC:	Date: 14 -	3/3?	Tooling: SPC (Y/N):		te: te:		j	Run	Start Stop	*NI	₹1* ₹2*
Sequence ID/ Work Center II	Operation D Description			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr											
D3636	Rev B U/R											
*1 \\n\*\ QC Quality Control	INS BE MI B1	SPECT RA 111689 D3636  LTS ARE GOOD BUT W  EL WILL CREATE A WO  14625 N 482	ORN RK ORDI	ER TO TURN INTO D36:	4				-			
110 *110* Packaging Packaging		dwg & Stock Location:	_	0.00 A	# 114825	3 <sup>-</sup> 13						

Work Order ID 114787  Thursday, March 13, 2014 2:31:11 PM				*114787*						Page 2		
Item ID: Revision ID:	D3636-11			Accept	*N900	04010	<b>)</b> /)*	Setup	Start	*N:	\$1*	
Item Name:	Shoulder Har	rness							Stop	*/\ <	30*	
Start Date:	3/12/2014	Start Qty: 1.00	*1*		Cust Item I	D:					.,	
Required Date	e: 3/13/2014	Req'd Qty: 1.00	*1*		Customer:	CHIGH03						
Reference:	RMA RA11	1689	•									
Approvals: Process		an:	Date:	Tooling: SPC (Y/N):	Date:Date:			Run	Start Stop	*NF	₹1*	
	QC:		Date:							*NF	32*	
Sequence ID/ Work Center	ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool # Plan	n Accep le Qty	pt Rej Oty	ect ]	Reject Number	Insp. Stamp	
120		QC21- Final Inspection	- Work Order Release	0.00							•	
*120*							M	しン	14-6	3-24		
Quality Control		Memo		0.00								
										m	Insp. Stamp  (4.3/13)	
					•							

## -Picklist Print

Thursday, March 13, 2014 1:28:24 PM

Work Order ID: 114787

\*114787\*

Parent Item:

D3636-11

\*D3636-11\*

Parent Item Name: Shoulder Harness

**Start Date:** 3/12/2014

Required Date: 3/13/2014

Start Qty: 1.00

Required Qty: 1.00

**Comments:** 

IPP Rev:A New Issue 07-09-11 JLM Verified By:EC

IPP Rev:B ECN 1050 rev.B as per dwg 08-01-10 DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3636-11		Manufactured	No				Each	1.0000		1			
*D3636-1	<b>  *</b>								**				

Shoulder Harness

Location Loc Qty Loc Code FG

> 104889 1

1 x ang 14- 3-13.

## RA111689 D3636-11 B104889 B97795

RECEIVED FEBRUARY 25, 2014 INSPECTED MARCH 7, 2014

CUSTOMER: HIGH TERRAIN HELICOPTERS LTD CONTACT: ANNA STEFANSKA SHIPPED FROM: NELSON, BC, CANADA

## Instructions for RA111689 D3636-11 B104889 B97795

- · Belts not warn
- Put back into stock as used parts
- Hold in quarantine till work order for used parts received

Time Estimate = 2 HOURS

**Departments Required:** Quality & production

Pictures Attached = N/A

**OTY INSPECTED** = x3 D3636-11 B104889

x1 D3636-11 B97795

## THIS INSTRUCTION SHEET MUST BE ATTACHED TO THE RESTOCKING WORK ORDER AT ALL TIMES!!!!